

RESEARCH INC.

---

June 21, 1989


Mr. John Lohmeyer  
NCR Corp.  
3718 N. Rock Road  
Wichita, KS. 76226

Dear John:

Please consider the possibility of an "alternate" design to the SCSI-II standard. The preferred alternative would be a ribbon contact design. The tab and receptacle seems to be a weak design, in that the Pin is very thin and can be susceptible to mechanical damage.

Thank you for your consideration.

Yours Truly,



David Wong  
AST RESEARCH, INC.  
Component Engineering  
714-476-3843

DW:cjo